TO FIT SIZE CHART

*Measurements refer to body size, not garment dimensions



R310X - TECHNICAL TROUSER 25.02.2016

	XS	S	М	L	XL	2XL	3XL	4XL	5XL
Waist in inches*	30	32	34	36	38	40	42	44	46
Waist in cm*	76	84	86	91	96	102	107	112	117
German clothing size	46	48	50	52	54	56	58	60	62
Leg inside in inches	32	32	32	32	32	32	32	32	32
Leg inside in cm	81	81	81	81	81	81	81	81	81

HOW TO MEASURE CHEST: Place the tape measure across the back, underneath the arms and then across the fullest part of the chest.

1 Inch = 2,54 cm